



Overview: Part of spill impact on 30" Nembe Creek Pipeline Right of Way at Boro. Picture was taken during Joint Investigation of 2nd August 2014.



Close-up: Loosened bolts on 30" Nembe Creek Pipeline at Boro. Picture was taken during Joint Investigation of 8th August 2014.