



Overview: Part of spill impact on 10" Diebu Creek – Nun River Pipeline Right of Way at Onyoma/Enewari. Picture was taken during Joint Investigation of 3<sup>rd</sup> July 2014



Close-up: Spill Point1 on 10" Diebu Creek – Nun River Pipeline at Onyoma/Enewari. Picture was taken during Joint Investigation of 3<sup>rd</sup> July 2014



Close-up: Spill Point2, 95.5m from Spill Point1, on 10" Diebu Creek – Nun River Pipeline at Onyoma/Enewari. Picture was taken during Joint Investigation of 3<sup>rd</sup> July 2014