



Overview: Oil bubbles sighted on 24" Cawthorne – Channel – Bonny Pipeline Right of Way at Adamakiri. Picture was taken during Joint Investigation of 23rd June 2014



Close-up: Illegal fitting on 24" Cawthorne – Channel – Bonny Pipeline at Adamakiri. Picture was taken during Joint Investigation of 26th June 2014