



Overview: Part of spill impact on 20" Otumara-Escravos Pipeline right of way at Adjudaibo. Picture was taken during Joint Investigation of 4th March 2014.



Close-up: Illegal fitting on 20" Otumara-Escravos Pipeline at Adjudaibo. Picture was taken during Joint Investigation of 5th March 2014.