



Overview: Part of spill impact on 24" Bomu-Bonny Pipeline right of way at Bodowest. Picture was taken during Joint Investigation of 8th March 2014.



Close-up: Illegal fitting on 24" Bomu-Bonny Pipeline at Bodowest. Picture was taken during Joint Investigation of 8th March 2014.