



Overview: Part of spill impact on 24" Nkpoku-Bomu Trans Niger Pipeline right of way at Biara. Picture was taken during Joint Investigation of 6th March 2014.



Close-up: Hacksaw cut on 24" Nkpoku-Bomu Trans Niger Pipeline at Biara. Picture was taken during Joint Investigation of 10th March 2014.