



Overview: Part of spill impact at Yokri Manifold8 at Yokri. Picture was taken during Joint Investigation of 7th March 2014..



Close-up: Position of pinhole leak on Yokri Manifold8 LP2 Bulkhead at Yokri. Picture was taken during Joint Investigation of 7th March 2014.