



		E 7.163506	Date 2014/03/06
		N 4.992478	Time 11:27:41 (UTC)
		Altitude 23.000 M	Speed 0.81 KPH

Overview: Part of spill impact on at ImoRiver2 Well28L Wellhead right of way at Umuedeokwara/Odagwa. Picture was taken during Joint Investigation of 6th March 2014.



		E 7.163538	Date 2014/03/06
		N 4.992445	Time 11:44:14 (UTC)
		Altitude 25.800 M	Speed 0.37 KPH

Close-up: Original location of missing Kerotex valve at ImoRiver2 Well28L Wellhead at Umuedeokwara/Odagwa. Picture was taken during Joint Investigation of 6th March 2014.