



Overview: Part of spill impact on 20" Otumara-Escavos Pipeline Right of Way at Ugboegungun. Picture was taken during Joint Investigation of 11th March 2014.



Close-up: Illegal fitting on 20" Otumara-Escavos Pipeline at Ugboegungun. Picture was taken during Joint Investigation of 11th March 2014.