



Overview: Illegal fittings on 28" Nkpoku-Bomu Pipeline at Akpajo. Picture was taken during Joint Investigation of 16th March 2014.



Close-up: Illegal fitting on 28" Nkpoku-Bomu Pipeline at Akpajo. Picture was taken during Joint Investigation of 16th March 2014.