



Overview: Part of spill impact on 10" Diebu Creek – Nun River Pipeline right of way at Peremabiri. Picture was taken during Joint Investigation of 20th March 2014.



Close-up: Failed clamp on 10" Diebu Creek – Nun River Pipeline at Peremabiri. Picture was taken during Joint Investigation of 19th March 2014.