



Overview: Part of spill impact on 28" Nkpoku-Bomu Pipeline right of way at Kpoghor. Picture was taken during Joint Investigation of 25<sup>th</sup> March 2014.



Close-up: Illegal fitting on 28" Nkpoku-Bomu Pipeline at Kpoghor. Picture was taken during Joint Investigation of 25<sup>th</sup> March 2014.