



		E 6.649131	Date 2014/03/25
		N 4.401516	Time 15:30:48 (UTC)
		Altitude 19.700 M	Speed 0.44 KPH

Overview: Part of spill impact on 6" Belema Pipeline right of way at Belema. Picture was taken during Joint Investigation of 25th March 2014.



		E 6.649130	Date 2014/03/25
		N 4.401398	Time 15:42:22 (UTC)
		Altitude 17.600 M	Speed 0.18 KPH

Close-up: Spill due to corrosion on 6" Belema Pipeline at Belema. Picture was taken during Joint Investigation of 25th March 2014.