



Overview: Part of spill impact on 28" Nkpoku-Bomu Pipeline right of way at B-Dere. Picture was taken during Joint Investigation of 17th March 2014.



Close-up: Illegal fitting on 28" Nkpoku-Bomu Pipeline at B-Dere. Picture was taken during Joint Investigation of 17th March 2014.