



Overview: Part of spill impact on 10" Diebu Creek Manifold – Nun River manifold right of way at Peremabiri. Picture was taken during Joint Investigation of 29th March 2014.



Close-up: Spill due to tear on 10" Diebu Creek Manifold – Nun River manifold at Peremabiri. Picture was taken during Joint Investigation of 30th March 2014.