



Overview: Part of spill impact on 12" Benisede – Brass Creek Pipeline right of way at Ojobo. Picture was taken during Joint Investigation of 27th March 2014.



Close-up: Illegal fitting on 12" Benisede – Brass Creek Pipeline at Ojobo. Picture was taken during Joint Investigation of 27th March 2014.