



Overview: Part of spill impact on 20" Rumuekpe – Nkpoku Pipeline right of way at Omusunu/Ibaa. Picture was taken during Joint Investigation of 9th April 2014.



Close-up: Drilled hole on 20" Rumuekpe – Nkpoku Pipeline at Omusunu/Ibaa. Picture was taken during Joint Investigation of 9th April 2014.