



Close-up: Illegal fitting on old 24" Nembe Creek Pipeline at Twoni. Picture was taken during Joint Investigation of 28th March 2014.



Close-up: Illegal fitting (non-leaking) on old 24" Nembe Creek Pipeline at Twoni. Picture was taken during Joint Investigation of 28th March 2014.