




Overview: Spill impact on 8" Mininta-Rumuekpe Pipeline Right of Way at Rumuekpe. Picture was taken during Joint Investigation of 14th May 2014.



Close-up: Illegal fitting on 8" Mininta-Rumuekpe Pipeline at Rumuekpe. Picture was taken during Joint Investigation of 17th May 2014.