



Overview: Part of spill impact on Yokri Wellhead79 Right of Way at Sokebolou. Picture was taken during Joint Investigation of 9th May 2014.



Close-up: Tampered valve on Yokri Wellhead79 at Sokebolou. Picture was taken during Joint Investigation of 9th May 2014.