




Overview: Spill impact on 28" Nkpoku-Bomu Pipeline Right of Way at B-Dere. Picture was taken during Joint Investigation of 21st May 2014.



Close-up: Drilled hole on 28" Nkpoku-Bomu Pipeline at B-Dere. Picture was taken during Joint Investigation of 21st May 2014.