



Overview: Part of spill impact on 28" Nkpoku-Bomu Pipeline Right of Way at Biara. Picture was taken during Joint Investigation of 22<sup>nd</sup> May 2014.



Close-up: Hacksaw cut on 28" Nkpoku-Bomu Pipeline at Biara. Picture was taken during Joint Investigation of 22<sup>nd</sup> May 2014.