



Overview: Part of spill impact on 10" Diebu Creek – NunRiver Pipeline Right of Way at Oporoma. Picture was taken during Joint Investigation of 25th May 2014.



Close-up: Hacksaw cut on 10" Diebu Creek – NunRiver Pipeline at Oporoma. Picture was taken during Joint Investigation of 25th May 2014.