



Closeup: Actuator cover removed on Soku Well48L Wellhead slot at Russia. Picture was taken during Joint Investigation of 28<sup>th</sup> May 2014.



Close-up: Tampered valve on on Soku Well48L Wellhead slot at Russia. Picture was taken during Joint Investigation of 28<sup>th</sup> May 2014.