



Overview: Part of spill impact on 28" Nkpoku-Bomu Pipeline Right of Way at B-Dere . Picture was taken during preliminary site visit on 11<sup>th</sup> May 2014.



Close-up: Illegal fitting on 28" Nkpoku-Bomu Pipeline at B-Dere. Picture was taken during Joint Investigation of 13<sup>th</sup> May 2014.