



Overview: Part of spill impact on 28" Nkpoku-Bomu Pipeline Right of Way at Ekporo. Picture was taken during Joint Investigation of 23rd May 2014.



Close-up: Illegal fitting on 28" Nkpoku-Bomu Pipeline at Ekporo. Picture was taken during Joint Investigation of 23rd May 2014.