



		E 7.222653	Date 2014/05/23
		N 4.720760	Time 10:13:01 (UTC)
		Altitude 10.500 M	Speed 0.24 KPH

Overview: Part of spill impact on 28" Nkpoku-Bomu Pipeline Right of Way at Ekporo. Picture was taken during Joint Investigation of 23rd May 2014.



		E 7.222813	Date 2014/05/22
		N 4.720623	Time 12:40:06 (UTC)
		Altitude 14.600 M	Speed 0.90 KPH

Close-up: Illegal fitting on 28" Nkpoku-Bomu Pipeline at Ekporo. Picture was taken during Joint Investigation of 22nd May 2014.