



Overview: Illegal hose on Soku Well21SL Wellhead slot Right of Way at Russia. Picture was taken during Joint Investigation of 28<sup>th</sup> May 2014.



Close-up: Tampered valve on Soku Well21SL Wellhead slot at Russia. Picture was taken during Joint Investigation of 28<sup>th</sup> May 2014.