



Overview: Part of spill impact on Okordia Manifold Right of Way at Ikarama. Picture was taken during Joint Investigation of 8th October 2014.



Close-up: Tampered flange nuts on Okordia Manifold at Ikarama. Picture was taken during Joint Investigation of 8th October 2014.