


Overview: Part of spill impact on 10" Diebu Creek – Nun River Pipeline Right of Way at Oporoma. Picture was taken during Joint Investigation of 16<sup>th</sup> October 2014.



Close-up: Hacksaw cut on 10" Diebu Creek – Nun River Pipeline at Oporoma. Picture was taken during Joint Investigation of 16<sup>th</sup> October 2014.