




Overview: Part of spill impact within cofferdam on 28" Bomu-Bonny Pipeline Right of Way at Bodo City. Picture was taken during Joint Investigation of 17<sup>th</sup> October 2014.



Close-up: Illegal fitting on 28" Bomu-Bonny Pipeline at Bodo City. Picture was taken during Joint Investigation of 17<sup>th</sup> October 2014.