



Overview: Part of spill impact on 28" Nkpoku – Bomu Pipeline at Gio. Picture was taken during Preliminary site visit of 15th October 2014.



Close-up: Hacksaw Cut on 28" Nkpoku – Bomu Pipeline at Gio. Picture was taken during Joint Investigation of 16th October 2014.