



Close-up: Cut section of 4" KoloCreek Well3T Flowline at Otusega. Picture was taken during Joint Investigation of 22nd October 2014.



Close-up: Cut section of 4" KoloCreek Well3T Flowline at Otusega. Picture was taken during Joint Investigation of 22nd October 2014.