



Overview: Part of spill impact on 18" Assa-Rumuekpe Pipeline at Egbeda. Picture was taken during Joint Investigation of 26<sup>th</sup> November 2014.



Close-up: Hacksaw cut on 18" Assa-Rumuekpe Pipeline at Egbeda. Picture was taken during Repair operations on 27<sup>th</sup> November 2014.