




Overview: Spill impact on 28" Bomu-Bonny Pipeline Right of Way at Bodo City. Picture was taken during Joint Investigation of 12th September 2014.



Close-up: Illegal fitting on 28" Bomu-Bonny Pipeline at Bodo City. Picture was taken during Joint Investigation of 12th September 2014.