



Close-up: Spill due to corrosion on Nun River Flowstation Sludge Discharge Line at Oporoma. Picture was taken during Joint Investigation of 16<sup>th</sup> September 2014.