




Overview: Part of spill impact on 28" Nkpoku-Bomu Pipeline Right of Way at B-Dere. Picture was taken during Joint Investigation of 20<sup>th</sup> September 2014.



Close-up: Wooden plug at spill point on 28" Nkpoku-Bomu Pipeline at B-Dere. Picture was taken during Joint Investigation of 20<sup>th</sup> September 2014.