



Overview: Part of spill impact on 8" Umuechem-Nkpoku Pipeline Right of Way at Omunwei. Picture was taken during Joint Investigation of 30<sup>th</sup> September 2014.



Close-up: Illegal fitting on 8" Umuechem-Nkpoku Pipeline at Omunwei. Picture was taken during Joint Investigation of 30<sup>th</sup> September 2014.