





Overview: Part of spill impact on 12" Imo River – Ogale Pipeline Right of Way at KomKom. Picture was taken during Joint Investigation of 4<sup>th</sup> October 2014.



Close-up: Illegal fittings on 12" Imo River – Ogale Pipeline at KomKom. Picture was taken during Joint Investigation of 3<sup>rd</sup> October 2014.



Close-up: Illegal fitting on 12" Imo River – Ogale Pipeline at KomKom. Picture was taken during Joint Investigation of 5<sup>th</sup> October 2014.