



Overview: Part of spill impact on 48" Forcados Crude Oil Export Pipeline Right of Way at Ogulagha. Picture was taken during Joint Investigation of 4<sup>th</sup> October 2014.



Close-up: Illegal fitting on 48" Forcados Crude Oil Export Pipeline at Ogulagha. Picture was taken during Joint Investigation of 4<sup>th</sup> October 2014.