



Overview: Part of spill impact on 16" Tunu-Brass Creek Pipeline Right of Way at Agbidiana. Picture was taken during Joint Investigation of 24th September 2014.



Close-up: Illegal fitting on 16" Tunu-Brass Creek Pipeline at Agbidiana. Picture was taken during Joint Investigation of 24th September 2014.