




Overview: Part of spill impact on 4" Obele-Ibaa Pipeline Right of Way at Ibaa/Omueze. Picture was taken during Joint Investigation of 6<sup>th</sup> December 2014.



Close-up: Hacksaw cut on 4" Obele-Ibaa Pipeline at Ibaa/Omueze. Picture was taken during Joint Investigation of 6<sup>th</sup> December 2014.