



Overview: Part of spill impact on 28" Nkpoku - Bomu Pipeline Right of Way at Gio. Picture was taken during Joint Investigation of 20th August 2015.



Close-up: Hacksaw cut on 28" Nkpoku - Bomu Pipeline at Gio. Picture was taken during Joint Investigation of 20th August 2015.