



Overview: Part of spill impact on 16" Tunu – Brass Creek Pipeline Right of Way at Agbidiana. Picture was taken during Joint Investigation of 21st August 2015.



Close-up: Illegal fitting on 16" Tunu – Brass Creek Pipeline at Agbidiana. Picture was taken during Joint Investigation of 21st August 2015.