



Overview: Part of spill impact on 28" Bomu-Bonny Pipeline Right of Way at Ayaminima. Picture was taken during Joint Investigation of 27th August 2015.



Close-up: Illegal fitting on 28" Bomu-Bonny Pipeline at Ayaminima. Picture was taken during Joint Investigation of 28th August 2015.