



Overview: Part of spill impact around Obedum Evacuation Plant. Picture was taken during Joint Investigation of 26<sup>th</sup> August 2015.



Close-up: Cut by unknown persons on Oil Storage Tank at Obedum Evacuation Plant. Picture was taken during Joint Investigation of 26<sup>th</sup> August 2015.