



9/6/2015 2:52:42 PM (+1.0 hrs) Lat=4.93715 Lon=5.70706 Alt=9ft MSL WGS-84

Overview: Part of spill impact on 20" Opukushi-BrassCreek Pipeline Right of Way at Tamogbene. Picture was taken during Joint Investigation of 6th September 2015.



9/6/2015 3:17:45 PM (+1.0 hrs) Lat=4.93721 Lon=5.70725 Alt=30ft MSL WGS-84

Close-up: Illegal fitting on 20" Opukushi-BrassCreek Pipeline at Tamogbene. Picture was taken during Joint Investigation of 6th September 2015.