



Overview: Part of spill impact on Diebu Creek Well1S Wellhead Right of Way at Peremabiri. Picture was taken during Joint Investigation of 4th September 2015.



Close-up: Location of missing Cameron Control Unit on Diebu Creek Well1S Wellhead at Peremabiri. Picture was taken during Joint Investigation of 4th September 2015.