



Overview: Part of spill impact on 20" Kolo Creek to Rumuekpe Pipeline Right of Way at Odau. Picture was taken during Joint Investigation of 25th August 2015.



Close-up: Hacksaw cut on 20" Kolo Creek to Rumuekpe Pipeline at Odau. Picture was taken during Joint Investigation of 25th August 2015.