



Overview : Part of spill impact on 8" Afam Well25 Flowline Right of Way at Egberu. Picture was taken during Joint Investigation of 2<sup>nd</sup> September 2015.



Close-up: Drilled hole on 8" Afam Well25 Flowline at Egberu. Picture was taken during Joint Investigation of 4<sup>th</sup> September 2015.